

INSTRUCTIONS FOR OPTIONAL MOUNTING OF LADDER

- Position ladder in well with hooks
 fitting securely over top lip. Generally front of well will have best access and less chance of interfering with grating.
- 2 Mark center of each top brace where it contacts rib of corrugated metal well. (See Fig. 3)
- **3** Remove ladder from well, lay marked braces over wood block and drill 5/16" hole thru each brace.
- Reposition ladder in well, drill
 3/16" hole into metal well by drilling thru holes in braces.
- Insert #14x1 Phillips pan head screws (2 provided) into holes and tighten.